

## Contents

- **General comments**
  
- **Nomenclature of the parts of a hob**
  - Normal and axial pitches
  - Normal and axial pressure angles
  - Helix angle
  - Gashes
  - Number of gashes
  - Cutting face
  - Tip and side relief
  - Outside diameter
  - Total length of hob
  - Centering bore
  - Collars and side faces
  - Tooth profile
  
- **Profile calculation**
  - Normal profile
  - The interference problem
  - Hobs with lowered pressure angle
  - Calculation of the semi-topping profile
  - Verifying the value of semi-topping
  - Protuberance and full radius
  
- **Multi-start hobs**
  
- **Multi-gash hobs**
  
- **Hob accuracy tolerances**
  
  
- **Material used to manufacture hob**
  - High speed steel
  - Sintered carbide
  
- **Recoating**
  - The CVD method
  - The PVD method
  - The electro-deposition process
  
- **Working condition**
  - Cutting speed
  - Feed and chip thickness

- The Hoffmeister formula
- Further consideration on chip thickness
- Reducing total hobbing cost
- Shifting
- Setting up a hob
- Consideration on workpiece errors
  
- **Cutting time and disposable hobs**
  
- **Dry cutting and carbide hobs**
  
- **Hob resharpening**
  
- **Skiving hobs**
  
- **Special profile hobs**
  - Worm wheel hobs
  - Hobs for splined shafts
  - Hexagonal profile hobs
  - Roller chain sprocket hobs
  - Fixed-position Hobs
  
- **Comment on hob manufacturing**
  
- **Inserted blade hobs**
  
- **Anomalies in the use of hobs and solutions**
  - Problem with the hob
  - Problem with the gear
  
- **Key to the most common abbreviations (acronyms)**